

Cleaning Instructions

Scale surfaces may be cleaned / disinfected as per local guidelines.

A solution of 1% sodium hypochlorite is suitable or Actichlor plus 10,000 ppm.

We recommend using alcohol-based wipes or similar when cleaning the scale.

Please do not use corrosive liquids, large amounts of water or high-pressure washers.

Do not disinfect by fogging or vapour.

Always disconnect the scale from the mains power supply before cleaning.